



**CIVIL AVIATION AUTHORITY OF SRI LANKA
AVIATION SAFETY NOTICE**

ASN No 106	Ref No: ATS/2008/07	File Ref: AS/12/15
------------	---------------------	--------------------

- Recipients
1. AOC Holders in Sri Lanka
 2. Owners of aircraft registered in Sri Lanka
01. Subject : **Registration of 406MHz Beacons used in aircraft registered in Sri Lanka.**
02. Nature : Compulsory
03. Issue no : 01
04. Status : New
05. Effective date : With immediate effect
06. Validity : Until further notice
07. Contact persons : For more details / clarifications/ about this ASN please contact Deputy Director, Aerodromes & Navigation Services (Tel. 2436324, e-mail-atulacaa@slt.net.lk), Address, Civil Aviation Authority of Sri Lanka, No 64, Galle Road Colombo 3.
08. Availability : A copy of this document is available at the Technical library of Civil Aviation Authority for reference.
09. Applicability : All aircraft registered in Sri Lanka.
10. Comments : Comments (if any) on the contents of this ASN may be forwarded to the Contact Persons. However the Aviation Safety Notice will come into effect on the date shown therein notwithstanding any objection or comment made by any person or party unless and until an amendment to the Aviation Safety Notice is issued afresh by the Director General of Civil Aviation

11. Notice : 1) The Telecommunication Regulatory Commission of Sri Lanka (TRCSL) has been designated as the registering agency for registration of 406MHz beacons in Sri Lanka.
- 2) The TRCSL has initiated registration of 406MHz beacons to the COSCAP-SRASAT International Beacon Registration Database (IBRD) with effect from 0001 UTC, 1st January 2009.
- 3) All 406MHz Beacons used in aircraft registered in Sri Lanka shall be registered in the IBRD through TRCSL.
- 4) The details of the 406MHz beacons already registered in IBRD shall also be provided to TRCSL for local registration.
- 5) Contact details of the person for registration of beacons are indicated below.
- i) Name: Ms. S.A.R. Kamalanayana
- ii) Mailing Address: Assistant Director/Spectrum Management, Telecommunication Regulatory Commission of Sri Lanka, No. 276, Elvitigala Mawatha, Colombo 08, Sri Lanka.
- iii) Telephone: +94112683843/+94112689345
- iv) Mobile: +94772620022
- v) Facsimile: +94112671444
- vi) E mail: adam.s@trc.gov.lk
12. History of Revision : Nil
13. Related ASNs : Nil
14. Action Required : For strict compliance by All AOC Holders in Sri Lanka/Owners of aircraft registered in Sri Lanka Using 406 MHz Beacons.
15. Check list : List of current ASN nos. are as follows

ASN No	Issue No	Date of Applicability	Remarks
ASN002	01	10.03.2000	nil
ASN003	01	18.08.2000	nil
ASN004	01	13.02.2001	nil
ASN005	01	26.03.2001	nil

ASN007	01	15.09.2001	nil
ASN008	02	16.11.2006	Replaced ASN 008 issue no 01
ASN009	01	18.02.2002	nil
ASN010	01	18.02.2002	nil
ASN011	01	18.02.2002	nil
ASN012	01	18.02.2002	nil
ASN013	01	08.02.2002	nil
ASN014	01	01.03.2002	nil
ASN015	01	01.03.2002	nil
ASN016	01	01.03.2002	nil
ASN017	02	10.03.2005	Replaced ASN 017 issue no 01
ASN018	01	20.03.2002	nil
ASN019	01	01.04.2002	nil
ASN021	01	01.04.2002	nil
ASN022	01	08.04.2002	nil
ASN023	01	01.06.2002	Replaced ASN no 003
ASN024	01	02.09.2002	nil
ASN025	02	15.10.2002	Replaced ASN no 001
ASN026	01	15.10.2002	nil
ASN027	01	12.12.2002	nil
ASN028	01	12.03.2003	nil
ASN029	01	21.03.2002	nil
ASN030	01	10.07.2002	nil
ASN031	01	15.07.2003	Replaced ASN no 006
ASN032	01	25.07.2003	nil
ASN033	02	25.08.2005	Replaced ASN no 033 issue no 01
ASN034	01	11.09.2003	nil
ASN035	01	12.09.2003	nil
ASN036	01	12.09.2003	nil
ASN037	01	13.10.2003	nil
ASN038	01	07.06.2004	nil
ASN039	03	05.01.2007	Replaced ASN no 039 issue no 02
ASN040	01	07.07.2004	nil
ASN041	01	16.07.2004	nil
ASN042	03	05.01.2007	Replaced ASN no 042 issue no 02
ASN043	02	12.08.2004	Amendment to ASN no 013
ASN044	02	13.03.2006	Replaced ASN no 044 issue no 01
ASN045	02	05.01.2007	Replaced ASN no 045 issue no 01
ASN046	01	14.09.2006	nil
ASN047	03	05.01.2007	Replaced ASN no 047 issue no 02
ASN048	02	05.01.2007	Replaced ASN no 048 issue no 01
ASN049	01	20.09.2004	nil
ASN051	01	20.09.2004	nil
ASN052	01	20.09.2004	nil
ASN053	03	15.11.2006	Replaced ASN 053 issue no 02
ASN054	01	01.04.2005	nil
ASN055	01	01.04.2005	nil
ASN056	01	01.12.2005	nil
ASN057	01	01.12.2005	nil
ASN058	01	01.12.2005	nil
ASN059	-	-	Not issued yet
ASN060	02	05.08.2005	Replaced Page no 01 of the attachment to the ASN no 060 issue no 01
ASN061	02	05.08.2005	Replaced Page no 01 of the attachment

			to the ASN no 061 issue no 01
ASN062	01	01.04.2005	nil
ASN063	01	20.12.2004	nil
ASN065	01	06.04.2005	nil
ASN066	01	16.05.2005	nil
ASN067	01	16.05.2005	nil
ASN068	01	18.05.2005	nil
ASN069	01	18.05.2005	nil
ASN070	01	18.05.2005	nil
ASN071	01	18.05.2005	nil
ASN072	01	18.05.2005	nil
ASN073	01	19.05.2005	nil
ASN074	01	19.05.2005	nil
ASN075	01	19.05.2005	nil
ASN076	01	16.06.2005	nil
ASN077	01	08.08.2005	nil
ASN078	01	21.12.2005	nil
ASN079	01	16.09.2005	nil
ASN080	01	07.11.2005	nil
ASN081	02	25.06.2006	Replaced ASN no 081 issue No. 01
ASN082	01	23.11.2005	nil
ASN083	01	01.12.2005	nil
ASN084	01	16.12.2005	nil
ASN085	01	05.01.2006	nil
ASN086	01	06.04.2006	nil
ASN087	01	06.04.2006	nil
ASN088	01	06.04.2006	nil
ASN089	01	10.05.2006	nil
ASN090	01	03.06.2006	nil
ASN091	01	15.06.2006	nil
ASN092	-	-	Not issued yet
ASN093	-	-	Not issued yet
ASN094	01	02.06.2006	nil
ASN095	01	25.09.2006	nil
ASN096	01	11.09.2007	nil
ASN097	01	22.09.2006	nil
ASN098	01	04.04.2007	nil
ASN099	01	09.10.2007	nil
ASN100	01	19.11.2007	nil

Parakrama Dissanayake
Actg. Director General of Civil Aviation and
Chief Executive Officer

Civil Aviation Authority of Sri Lanka,
No. 64, Supreme Building,
Galle Road, Colombo 03.
Telephone: 94 11 2433213, Fax: 94 11 2440231
E-mail: sldgca@slt.lk